


CVe Monitor Cloning

Requirements: Installed & Configured OnDemand Software, the source Monitor with the data to be copied, the new (destination) Monitor, 1 USB to Mini USB cable to connect the Monitor to you PC.



For complete OnDemand software instructions, please refer to the User Guide.
For technical assistance please email: SystemMonitoring@procomps.com.